


Calandra Racing Concepts	CRC4000	Advanced Electronics Black Diamond LV	2.1 software or higher	Has a blinking blue light when the throttle is in neutral and when set to the no-timing profile #1
--------------------------	---------	--	------------------------	--



Calandra Racing Concepts	CRC4002	Advanced Black Diamond	2.1 software or higher	Has a blinking blue light when the throttle is in neutral and when set to the no-timing profile #1
--------------------------	---------	---------------------------	------------------------	--




Castle Creations	Mamba Max Pro	V1.26
------------------	---------------	-------




Graupner GmbH & Co.	GM-Genius 120	Yellow, Red, and Green blink fast and at the same time in neutral position when the zero mode is active	V13.0	Users must use Mode 0-5 after factory reset or after delivery. Modes 6-9 have high speed timing, no LED blinking. No high speed timing is allowed to set with PC-software. Mode 2 is factory setting. If high speed timing, no LED blinking.
---------------------	---------------	---	-------	--

Graupner GmbH & Co. GM-Genius 150, GM-Genius 75, GM-Genius 90 approved all as picture below.



(Motorconfiguration #1)
Connecting a brushless motor to the controller
Reserved 2 = 1 must be set! (factory setting)



KO Propo	40051	VFS-1 BMC Ver 1.5	Contact Mfg for Firmware Upgrade	Must use zero timing and zero Advanced Profile signified by blinking LED on switch.
----------	-------	----------------------	----------------------------------	---



Losi	LOS9500	1/10th Xcelorin Brushless ESC	01.01.30	Must use zero timing and zero Advanced Profile signified by blinking color LED
------	---------	-------------------------------	----------	--



LRP	LRP80100		Ai Brushless Reverse	No software
LRP	LRP80150		Ai Brushless Pro Reverse	No software
LRP	LRP80400		SPX Brushless Super Reverse	No software
LRP	LRP80410		Crawler ESC	No software
LRP	LRP80500		Sphere Brushless ESC	No software
LRP	LRP80705 SPX Zero		Non – Updateable Zero timing when in profile 0 and Red LED is flashing	



LRP	LRP809050	LRP SXX "Version 2" Competition Brushless ESC	N/A	Must use zero timing and zero Advanced Profile signified by blinking blue LED when in neutral.
-----	-----------	---	-----	--



LRP LRP809055 LRP SXX :

Must use zero timing and zero Advanced Profile signified by blinking blue LED when in neutral.



LRP LRP80915 SXX Stock Spec V2

Desc: For Spec zero timing mode, both mode 2 (torque) and mode 3(timing) must be set to zero. Blue LED will blink in neutral



Novak NOV1709 GTB 2 Sportsman Racing Brushless ESC

Desc: When all timing is OFF, then white LED will be OFF to indicate no timing active.



Novak	NOV1710	Novak GTB	No software	<input type="checkbox"/>
Novak	NOV1711	Novak GTB Spectrum	No software	<input type="checkbox"/>
Novak	NOV1712	Novak Slyder Drift	No software	<input type="checkbox"/>
Novak	NOV1731	Novak Havoc 1 Cell	No software	<input type="checkbox"/>
Novak	NOV1732	Novak Havoc Sport	No software	<input type="checkbox"/>
Novak	NOV1733	Havoc 3S Brushless ESC	(this ESC can be run on 2S or 3S) No timing built into ESC	<input type="checkbox"/>



Novak NOV1735 Novak Havoc Pro No software


Novak	NOV1740	Kinetic Racing Brushless ESC	Version 1.0 software or higher	ESC must be set at Timing Level = 1 or Zero Timing (default)
-------	---------	------------------------------	--------------------------------	--



Novak NOV1741 as the above image

Novak	NOV1741	Kinetic 1S Racing Brushless ESC	Version 1.0 software or higher	ESC must be set at Timing Level = 1 or Zero Timing (default) **Note, this ESC will be shipping in August 2010
-------	---------	---------------------------------	--------------------------------	--


Novak	NOV1745	Havoc Pro SC Brushless ESC	Version 1.0 software or higher	ESC must be set at Timing Level = 1 or Zero Timing (default)
-------	---------	----------------------------	--------------------------------	--



ORCA	OBS080R1	Vritra VC4 Pro SPEC ESC	Blinking green LED when the ESC is setup with no turbo and no timing. When there is timing, or timing and turbo in the ESC, the LED is Solid Red	
------	----------	-------------------------	--	--




ORCA	OBS1680R	Vritra VTC Pro SPEC ESC	Blinking green LED when the ESC is setup with no turbo and no timing. When there is timing, or timing and turbo in the ESC, the LED is Solid Red	
------	----------	-------------------------	--	--



Speed Passion	Cirtix Stock Club Race # 12280	No Timing adjustments-no LED	Non-Programable	
Speed Passion		EXT98802LPF	GT-LPF 2.0 ESC (Carbon, Silver or Blue Version)	508
Speed Passion		EXT98802LPF	LPF 2.1 ESC (Carbon, Silver, Blue)	V508
Speed Passion		EXT98802Pro	GT-Pro 2.0 ESC (Carbon, Silver or Blue Version)	508
Speed Passion		EXT98802PRO	PRO 2.1 ESC (Carbon,Silver,Clue)	V508
Speed Passion	EXT98802LPF	GT-LPF 2.0 ESC (Carbon, Silver or Blue Version)	508	Must use zero timing and zero Advanced Profile signified by blinking LED

All the above Speed Passion EXT98802 use the same case as image below:



Tekin	TT1152	Tekin RS ESC	212 ** NOTE NEW SOFTWARE PROFILE**	SPEC – Non Timing Mode is displayed by LED 3&5 blinking when armed and in neutral position. AVAILABLE 10/20/2010
-------	--------	--------------	------------------------------------	--



Tekin	TT1153	Tekin RS Pro	212 ** NOTE: NEW SOFTWARE PROFILE	SPEC – Non Timing Mode is displayed by LED 3&5 blinking when armed and in neu
-------	--------	--------------	-----------------------------------	---

